



PHASE 2 NOTES:

1. BLUE DIMENSIONS REPRESENT CHANGES.
2. GREY DIMENSION ARE FOR REFERENCE AND HAVE NOT CHANGED FROM PHASE 1.

SIMULATION:

1. USE SIMULATIONXPRESS OR SOLIDWORKS SIMULATION TO ANALYZE AND DETERMINE THE FACTOR OF SAFETY OF THE PART.
2. RECORD THE FACTOR OF SAFETY FOR FOR THE PART IN THE MODEL MANIA REGISTRATION PROGRAM.

NOTES:

1. ALL DIMENSIONS ARE IN MILLIMETERS
2. MATERIAL: PLAIN CARBON STEEL

THIRD ANGLE PROJECTION



PROPRIETARY AND CONFIDENTIAL		
THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF SOLIDWORKS. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF SOLIDWORKS IS PROHIBITED.		
DRAWN BY:	NAME	DATE
MATERIAL:	MAS	12-30-12
	Plain Carbon Steel	

MODEL MANIA 2013
Phase 2